



NEW WESTMINSTER

June 23, 2020

ENQUIRIES AND RESPONSES #1
NWIT-20-10
2020 Sewer CCTV Inspection Program
New Westminster, BC

ANSWERS TO SUBMITTED QUESTIONS

- Q1 Could you please provide a sample of the manhole inspection format?
A1 [Attached is example of manhole inspection report.](#)

END of Enquiries and Responses #1

Yours truly,

Heather M. Rossi
Intermediate Buyer

Sample Manhole Inspection Report

Inspected By	-----	Inspection Date	-----
Nearest Address	-----	Nearest Street	-----
Report Number	-----	Number of Connections	-----
Manhole Number	-----	Depth	2.5 m
Manhole Rating	Good, No Work Required	Manhole Steps	Good
Cover / Frame Condition	Good	Wall Condition	Good
Surface Type	Other	Bench Condition	Good
Debris	Clean	Debris Comments	none
Surcharge	No	Surcharge Comments	none
Infiltration	None	Infiltration Comments	none

